
ILANE 4.0 INSTALLATION INSTRUCTIONS | MARCH 2023





WEVER & DUCRÉ


LIGHTING


ILANE 4.0

















- 1 Inner profile surface must be cleaned and free from grease / dust.
 - LED COB strip can be cut to length:


 10W/M version = every 50,00mm
 15W/M version = every 31,20mm
- 3 Adhesive side on the LED COB strip for easy fixation.
- 4 LED COB strip needs to be pushed on gently and not with tools.
- **5** Fix the electrical connector to the COB LED strip as illustrated.
- The non-connector side of the LED COB strip should be electrically isolated so that the LED copper conductors cannot touch the profile.
- Cable can go through end cap with hole or alternatively a hole can be drilled in the profile to enter with the cable through the back side.
- 8 LED COB strip polarity needs to be respected when connecting to a driver.

ILANE 4.0 INSTALLATION INSTRUCTIONS | MARCH 2023


LED COB strip connectors:

from strip to driver











from strip to strip: making continuous lines





LED COB strip can be cut to length:

10W/M version = every 50mm 15W/M version = every 31,20mm



When cutting the strip it is important to cut precisely between 2 LEDs. When an LED is exposed there is no phosphor covering the side which will show blue light coming out of the cut side of the strip.

