




# TRACE mini on STREX

INSTALLATION INSTRUCTIONS | JANUARY 2026






## DIMENSIONS




## MOUNTING INSTRUCTION

- 1 Push the fixture into the track at the preferred location.




Note: it's not allowed to slide the device in the track. If you want to change the location of the device, please pull the device out of the track and install it on the correct position.




# TRACE mini on STREX

INSTALLATION INSTRUCTIONS | JANUARY 2026




## DISMOUNTING INSTRUCTION Light source & driver

- 1** Unscrew the top screws and remove the lid.
- 2** Disconnect the wires and remove the driver board.
- 3** Pull out the snoot by using a flat tool and remove the lens.
- 4** Unscrew the screws, disconnect the wires and remove the light source.




The driver is replaceable by Wever & Ducré or by a professional with explicit authorisation. For more information please contact your local Wever & Ducré customer service point.



The light source is replaceable by Wever & Ducré or by a professional with explicit authorisation. For more information please contact your local Wever & Ducré customer service point.



This luminaire contains a light source with the energy class G.



Use green electricity to light up your luminaire.