


STREX POWER FEED


INSTALLATION INSTRUCTIONS | FEBRUARY 2024

DIMENSIONS






POWER FEED 90014153 / 90014154


cable specification




tracks



A grommet is necessary when the track needs to be drilled to enter with a cable.



power feed connection through side



power feed connection through top

