



RL7050959

BRASS LOWER CAP



2097/18



2097/30

WARNING! When installing and whenever acting on the appliance, ensure that the power supply has been switched off.
For the installation of the spare-part, it is necessary to consult a qualified electrician.